

ECR #: P1

Tracker #: 3

Status: Ratified

Title: Correction to Figure 3.17

Release Date: June 2, 1997

Impact: Clarification Only

Spec Version: NLX 1.2

Summary:

Change Figure 3.17 to correct the drawing.

Background:

The figure as shown in version 1.2 of the specification has incorrect corners for the I/O aperture. If a chassis vendor were to develop a chassis to this diagram, it would introduce unnecessary complications.

Change Current Specification As Shown:

Replace Figure 3.17 with the following diagram.




Figure 3.17: Chassis Back Panel I/O Shield Opening